


64041 Motor Layout

This is a common motor layout for double reclining mechanisms like the:

- 64041 Nolan Godiva Power Double Reclining Sofa



Key

- ❶ Control Buttons & Cord
PART-64041-CONTRL BUTTON
- ❷ Motor
PART-64041-MOTOR
- ❸ Split Motor Cord
PART-64041-MOTOR CORD
- ❹ Transformer Power Cord
PART-64041-POWER CORD

Troubleshooting

- + Check your breaker box for any flipped breakers
- + Unplug and re-plug all connections
- + Check cords closely to ensure that the reclining mechanism has not cut or crushed them
- + Check along cords to ensure that there are no exposed wires

64041 Motor Layout - Interchangeable Parts

The parts for the 64041 Motor Layout can be interchanged following the guide below:

Control Buttons & Cord

- PART-64041-CONTRL BUTTON

Motor

- PART-64041-MOTOR

Split Motor Cord

- PART-64041-MOTOR CORD

Transformer Power Cord

- PART-18585-POWER CORD